EXHIBIT A



911 H Street Fresno, CA 93721 (559) 621-4181 FAX (559) 498-4323

Alarm Date and Time 1/20/2016 3:11:42PM

Location 648 N VAN NESS AVE, FRESNO Incident Number 2016-6003909

Incident Narrative:

Incident Reporting Officer: James D Perkins

On Wednesday, 20 January 2016 at 15:12:41, units T04, E09, E04, E05, T09, BC01, E03, BC03, I04, I01, E05, E07, I02 and T04 responded to a reported 1 - Fire at 648 N Van Ness AVE, Fresno, CA 93728. Upon arrival a 111 - Building fire incident was found.

The primary property use is 419 - 1 or 2 family dwelling.

Unit E03, the first arriving unit, arrived at 15:15:10. The last unit on scene, I02, cleared the scene at 20:28:57.

Actions taken by the primary responding units were: 11 - Extinguish; 20 - Search & rescue, other; 32 - Provide basic life support (BLS); 52 - Forcible entry; 81 - Incident command and 86 - Investigate.

A total of 14 units and 38 personnel responded to this call.

Fresno City Fire Department Structure Fire, Incident #6003909 Engine 3A: FF Perkins, Capt. Palmer, FFS Tatham, FF Gonzalez

Synopsis:

This report details a fire on 01/20/2016 at 15:11 hrs. in a two-story house built in 1928, located at 648 N Van Ness Avenue, Fresno, CA 93701.

The fire burned a portion of the front room on the A side of the building, and one male patient was located inside the home, and extricated to the front yard where it was determined he had

CRMC via American Ambulance.

Source of Activity:

On 01/20/2016 at 15:11 hrs, E3 responded to a residential structure fire in the area of N Van Ness and Bremer. We were just clearing a medical aid call approximately six houses south of that location, at 550 N Van Ness, giving us very limited response time. From the location of the Medical Aid, we visualized a woman frantically waiving at us and noticed light smoke in the area. I informed Communications that we were clear of the medical aid, and responding to the fire call on Fire 1.

Initial Observations/Actions:

E3 was first to arrive, and noted a two-story single family residence with light smoke showing from the first floor. The crew of E3 first had to make access through a heavy duty wrought-iron fence. The fence contained a rolling gate and swinging man-gate, which were both locked. Several attempts were made by the crew of E3 to breach either gate before the rolling gate was breached and slid out of the way, giving access to the driveway. E9 arrived and I assigned them to assist with Fire Attack and establish 2-out.

BC1 arrived and we did a face-to-face. I informed him of what I had thus far, and what the assignments were. BC1 assumed Incident Commander and assigned me Deputy Incident Commander.

FF Gonzalez (E3) pulled a 1 ½" hose line down the driveway and towards the front door, and FF Douglas (E9) pulled a second 1 ½" hose line. Members from E3 and E9 attempted to breach the front door on the A side (west) of the building using hand tools. They noted that it appeared to be highly reinforced and extremely

Print Date: 6/17/2019 Page 1 of 9



911 H Street Fresno, CA 93721 (559) 621-4181 FAX (559) 498-4323

difficult to breach. After several attempts, I advised them of a second door on the B (north) side of the building, which I noticed during my 360 walk around. Efforts from E3 and E9 crews were then focused on the door on the B side of the building. It was noted that this door was also reinforced from behind, causing a delay in gaining access to the house. Note- I observed a third door to the rear of the house(C side), but deemed that door not ideal due to the fact that it was also locked, and a large barking dog could be heard on the inside of it. I assigned T4 to assess for ventilation, and their crew of 4 personnel split into two groups of 2. FF Otto (T4) utilized the chainsaw to breach the front (A side) door, which still took several minutes to accomplish. At the same time the A side door was breached with a chainsaw, crews also breached the B side door with hand tools. Upon further investigation both doors were found to have been reinforced and barricaded from the inside.

E4 arrived and was assigned to stage by a hydrant. T9 also arrived and was assigned RIC. With both the A side and B side doors breached now, the Fire Attack group took their hose line to the A side door, where they encountered a relatively small amount of fire on the floor just inside the A side door. Before making entry they had to remove a plastic folding table, which had been pushed up against the back side of the door. Captain Palmer from E3 (Fire Attack) informed me that at one point he encountered a locked bathroom window, unlocked it and slid the window open, then removed the screen in an attempt to ventilate the immediate area.

When the door on the B side of the house was removed, it was noted that a second door was leaning up against the back side of that door. Also noted was a 5-gallon propane tank placed on the first stair going up. Capt. Garnier (T4), FFS Sickler (T4) and FFS Philbin (T4) were assigned to Search Group. They began their search by going from the door on the B side, up the stairs to the second floor. They reported the second floor all-clear, and that it appeared to be just storage.

FF Douglas (E9) located a door just inside the side B door and to the right. A few attempts were made to breach this door before it gave way, noting there was a large metal piece of machinery pushed up against the inside of the door. The door and machinery were removed so access into the house could be made. I was told by the Incident Commander (BC Tuggle) to make an announcement for crews to be on the lookout for potential booby-traps and hazards, and the announcement was made over the radio.

The Search group moved down to the first floor of the house and located a male patient in a back room. Capt. Garnier and FFS Philbin removed the patient to the front yard, where he was determined to have

E4 was assigned to bring their personnel up to assume Medical group. Crew members from E4 joined by American Ambulance, and two members from E4

Fire Attack declared the fire under control, and they were asked to remain outside the house. Search Group completed a search of the remaining areas of the house, in which no further patients were located.

At that point the FFD Fire Investigations team and FPD Homicide took control of the scene.

Summary of Statements: See I01 Perez's report for Statements

Scene Examination: Refer to I01 Perez's report.

Exposures

The immediate fire exposure consisted of the second story of the house. As for a potential exposure, there was a residence to the south, and a residence to the north of the house. Neither was ever in eminent danger.

Conclusion:

Refer to I01 Perez's report.



911 H Street Fresno, CA 93721 (559) 621-4181 FAX (559) 498-4323

Company Narratives:

Company Reporting Officer: Timothy J Fulmer

On Wednesday, 20 January 2016 at 15:12:41, unit E04 responded to 648 N Van Ness AVE, Fresno, CA 93728. Upon arrival a 11 - Structure Fire incident was found.

Unit E04 arrived at 15:17:58 with 3 personnel

The actions taken by this unit were: 32 - Provide basic life support (BLS); 73 - Provide staffing and 92 - Standby.

E4 arrived on scene and was assigned to water supply. E4 secured a water supply on Bremer and stood by at the hydrant. While standing by the hydrant, I heard T4 stated that they had a patient and that they were bring him out to the front. Command requested E4 crew to come to the front and assume patient care. E4 crew assisted EMS and FF Vasquez with patient care which included

Company Reporting Officer: Kenneth A Garcia

On Wednesday, 20 January 2016 at 15:12:41, unit E05 responded to 648 N Van Ness AVE, Fresno, CA 93728. Upon arrival a 11 - Structure Fire incident was found.

Unit E05 arrived at 00:00:00 with 4 personnel

The actions taken by this unit were: 93 - Cancelled en route.

Company Reporting Officer: Douglas M Garifo

On Wednesday, 20 January 2016 at 15:29:21, unit E07 responded to 648 N Van Ness AVE, Fresno, CA 93728. Upon arrival a 11 - Structure Fire incident was found.

Unit E07 arrived at 00:00:00 with 3 personnel

The actions taken by this unit were: 93 - Cancelled en route.

Company Reporting Officer: Paul B Garnier



911 H Street Fresno, CA 93721 (559) 621-4181 FAX (559) 498-4323

On Wednesday, 20 January 2016 at 15:12:41, unit T04 responded to 648 N Van Ness AVE, Fresno, CA 93728. Upon arrival a 11 - Structure Fire incident was found.

Unit T04 arrived at 15:17:21 with 4 personnel

The actions taken by this unit were: 11 - Extinguish; 21 - Search and 22 - Rescue, remove from harm.

On Wednesday January 20, 2016, at approximately 1511 hours .T-4 responded to a residential structure fire at 648 N. Van Ness Ave. in the city of Fresno, county of Fresno, state of California. This is Fresno Fire department incident # 6003909. T-4 arrived and was given the assignment to make an assessment for possible ventilation. I, Captain Garnier had the crew of T-4 get the tools necessary for ventilation ready. I completed a 360 of the structure and made a face to face with command. During my 360, I shut off power to the structure at the main electrical panel and relayed this information to command via my hand held radio. I met the crew of T-4 on the exterior of the structure, on the "A" side, where they were forcing entry to the front door with a chainsaw. The front door was opened and a handline was brought through that opening. The E-5 FF had a hard time extinguishing a small fire right inside the front door. It appeared that there was a flammable liquid, or possibly melted plastic, at the front door entrance, which would not extinguish easily. It also appeared that the front door had been barricaded from the inside, as well as nailed shut. I also tried to further open the broken glass window next to the front door, but this window had heavy gauge wire mess attached to the inside of it. I notified command via a face to face conversation that this building was a little odd, and that we should be careful. I noted that the doors and some windows were barricaded, there are security cameras in numerous places, and a large dog inside the rear entry point of the structure. T-4 was then assigned to conduct a primary search of the structure. FFS Sickler and FF Otto entered on the "B" side entrance and searched the upstairs with a negative result. Myself, and FFS Philbin searched the downstairs and entered from the same "B" side entrance. FFS Philbin and I located a victim in the "B/C" corner of the structure. I radioed that we found a victim and were bringing him out. Upon retrieving the victim we noticed that he had what appeared to This was relayed to command. T-4

turned Patient care over to E-4 and T-4 resumed its search with further

Company Reporting Officer: Paul B Garnier

On Wednesday, 20 January 2016 at 16:47:44, unit T04 responded to 648 N Van Ness AVE, Fresno, CA 93728. Upon arrival a 11 - Structure Fire incident was found.

Unit T04 arrived at 16:47:47 with 4 personnel

The actions taken by this unit were: 70 - Assistance, other.

Company Reporting Officer: Jonathan C Lusk

On Wednesday, 20 January 2016 at 15:12:41, unit T09 responded to 648 N Van Ness AVE, Fresno, CA 93728. Upon arrival a 11 - Structure Fire incident was found.

Unit T09 arrived at 15:18:04 with 4 personnel

The actions taken by this unit were: 73 - Provide staffing and 75 - Provide equipment.

T09 assigned as RIC.

T09 secured all utilities gas/electric.

Company Reporting Officer: Richard Perez



911 H Street Fresno, CA 93721 (559) 621-4181 FAX (559) 498-4323

FFD EVENT #: 16-003909 FPD CASE #: 16-004815 CLASSIFICATION: INCENDIARY

DATE: Wednesday, January 20, 2016 @ 1511 hours LOCATION: 648 N. Van Ness Ave., Fresno, CA, 93728

VICTIM:

REPORTING OFFICER: Perez, R

SYNOPSIS

This report documents my actions and findings related to a residential fire investigation.

The fire caused moderate fire damage.

There was one fatality identified at the time of this report.

The cause of this fire is classified as INCENDIARY.

No suspects have been identified at the time of this report and this incident remains under investigation.

SOURCE OF ACTIVITY

On Wednesday, January 20, 2016 at approximately 1511 hours Fresno County Dispatch received a 911 emergency call reporting a residential fire at 648 N. Van Ness Ave., Fresno City in the county of Fresno. A residential fire alarm assignment responded.

First arriving fire units arrived on scene at approximately 1515 hours. Initial size-up reported people waving in Engine Company 3, light smoke showing. A working fire notification was broadcast at approximately 1515 hours.

At approximately 1528 hours a Fire Investigator response was requested.

At approximately 1531 hours, while working my normal schedule with the Fresno Fire Department as Fire Scene Investigator I01, I responded to the incident with Fresno County Dispatch. I responded code two from 3187 W. Belmont Ave., Fresno City, CA. I arrived at the fire scene at approximately 1539 hours. I cleared the fire scene at approximately 2023 hours.

OBSERVATIONS/ACTIONS

Upon my arrival I observed numerous FFD apparatus and personnel in suppression mode of a residential fire. I did not observe any active fire behavior. I only witnessed smoke coming from the residence.

I initially made contact with suppression Incident Commander, Battalion Chief Tuggle, T. #07297 (CHIEF TUGGLE) and advised him of my presence. CHIEF TUGGLE briefed me as to his initial findings and requested that I order additional police officers for the civilian casualty that presented late in the suppression operation.

I assisted with the fire scene origin and cause by documenting the fire scene with digital photographs and processing the area of origin.

Company Reporting Officer: Jay S Tracy

Print Date: 6/17/2019 Page 5 of 9



911 H Street Fresno, CA 93721 (559) 621-4181 FAX (559) 498-4323

FIRE INVESTIGATIONS REPORT

FFD EVENT #: 16-003909

CASE #: 16-004815

CLASSIFICATION: Incendiary

DATE: Wednesday, January 20, 2016 @ 1511 hours

LOCATION 648 N Van Ness Ave., Fresno, CA, 93728

VICTIM:

REPORTING OFFICER: Tracy, Jay #F685

REPORT #: 16-003909.JT.1

SYNOPSIS

This report documents my actions related to an occupied residential fire investigation.

The fire caused moderate fire damage.

There was one fatality, related to this fire incident, identified at the time of this report.

The classification of this fire is incendiary.

No suspects have been identified at the time of this report.

SOURCE OF ACTIVITY

On Saturday, January 20, 2016 at approximately 1511 hours, Fresno County Dispatch received a 911 call reporting an apartment fire at 648 North Van Ness Avenue, Fresno City in the county of Fresno. A full residential first alarm assignment was dispatched at 1512 and three engines, two trucks, two battalion chiefs and one EMS unit responded.

The first fire units arrived on scene at approximately 1515 hours. Initial size-up reported a two story, single-family, residential structure with smoke showing from the A-B corner. Smoke was witnessed coming from the front porch area and the subfloor below the front window near the A-B corner. A working fire notification broadcast at approximately 1515 hours.

At approximately 1512 hours, while working my normal schedule with the Fresno Fire Department as Staff Investigator – I04, I responded to the incident code 2 from Blackstone Ave and Olive Ave. after clearing from another detail in the immediate area. I arrived at the fire scene at approximately 1515 hours. I cleared the fire scene at approximately 2200 hours.

OBSERVATIONS/ACTIONS

Upon my arrival, I observed one FFD apparatus and suppression personnel engaged in initial investigation and size up. The FFD suppression crews had to force entry of a man gate and vehicle gate to gain access to the residence. More FFD apparatus arrived after my arrival and began suppression efforts. Scene Investigator – I01 Perez, RJ #F363 also arrived.

I witnessed light smoke coming from the Alpha side of the structure, front door and front window area. The smoke appeared to be coming from the A-B corner of the residence near the subfloor below the window. Forced entry was attempted at the front door without success; the door seemed to be heavily fortified and eventually required the use of a chainsaw to gain entry. A few minutes later flames could be seen in the front window. Ingress was also attempted on the Bravo side door. This door also proved difficult to breach due to apparent fortification. Entry was obtained about the same time from both portals. Fire was present in the front room near the front window and door. The fire seemed difficult to extinguish; the fire was easily "pushed" with the fire stream.

While gathering witness statements, I witnessed FFD suppression crews extricate a victim, later identified as

Print Date: 6/17/2019 Page 6 of 9



911 H Street Fresno, CA 93721 (559) 621-4181 FAX (559) 498-4323

from the residence. The victim was extricated out the front door and placed on the driveway where BLS measures were initiated by FFD suppression crews. I noted the and had signs of being inside the structure during the fire. I then went to the street to notify EMS that a victim had been extricated and their assistance would be required. Three notification attempts were made before EMS responded. I also requested the Uniformed Patrol Officer from the Fresno Police Department (FPD), who was also present shortly after my arrival and assisted with traffic control initially, to assist in clearing the roadway for EMS who would be transporting soon.

I returned to the location of the victim and made contact with Scene Investigator Perez. As we began to develop a plan we were advised by Fire Captain Fulmer, Tim that the victim had

At this time I logged on with FPD and requested assistance from FPD dispatch. Contact was made again with the Uniformed Patrol Officer and a request was made to assist in locking down the scene due to the nature of the

Scene Investigator Perez and I then made contact with the FFD Incident Commander, Battalion Chief – BC1 Tuggle, Todd #F07297 and requested that all non-essential efforts inside the residence be stopped and access to the residence be denied. The residence was secured and no personnel entered. Staff Investigator – I02 Wilding, Lee #F634 arrived to assist with the investigation. Investigator Wilding was assigned the Investigation Team IC position. Fresno PD Homicide eventually arrived and assisted with the investigation. FPD homicide detectives Rivera #P1146 and Dodd #P280 later arrived on scene. FPD Lieutenant Farrah and Sergeant Bowlin also arrived and assisted.

I further assisted with the investigation by conducting interviews, assisting with documenting of the fire scene with digital photographs and sketch of the residence, entry/exit record keeping and processing the area of origin. For further details on my actions and finding on this fire incident refer to my investigations report 16-003909.JT.1.

Company Reporting Officer: Anthony R Vasconcellos

On Wednesday, 20 January 2016 at 15:12:41, unit E09 responded to 648 N Van Ness AVE, Fresno, CA 93728. Upon arrival a 11 - Structure Fire incident was found.

Unit E09 arrived at 15:15:37 with 3 personnel

The actions taken by this unit were: 11 - Extinguish; 51 - Ventilate and 52 - Forcible entry.

We arrived shortly after engine 3 and were assigned to assist with fire attack and establish two out. Upon arriving we approached the scene to see Engine 3 crew trying to force entry on the A side door, after a few attempts we spottted a door on the B side and attempted to breach the B side door as the A side was difficult due to being reinforced on the interior. We encountered the same scenario with the B side door as well. After multiple attemps with the irons we were able to open the B side door which had been reinforced on the inside as well. That door led to an upstairs portion of the residence and to the right of the stairs inside the B side doorway was a door that lead to the living room/front room of the residence which also had a door that I kicked in, it was also barricaded with items on the interior. At this point another company forced the A side door and we repositioned the hoselines to the A side, E3 crew and E9 FF entered the A side for fire attack, Specialist 9 and myself established 2 out. After fire attack knocked down the fire in the front room I witnessed Truck 4 crew carrying a victim through the front room and out of the A side door onto the driveway. We maintained 2 out and started the fan at the A side door for ventilation and entered the front room to finalize extinguishment of the residence.

Company Reporting Officer: F Leland Wilding



911 H Street Fresno, CA 93721 (559) 621-4181 FAX (559) 498-4323

On Wednesday, 20 January 2016 at 15:37:25, unit I02 responded to 648 N Van Ness AVE, Fresno, CA 93728. Upon arrival a 111 - Building fire incident was found.

Unit I02 arrived at 15:42:53 with 1 personnel

The actions taken by this unit were: 80 - Information, investigation & enforcement, other.

FFD EVENT #:

16-003909

CASE #:

16-004815

CLASSIFICATION:

Incendiary

DATE:

Wednesday, January 20, 2016 @ 1511 hours

LOCATION:

648 N. Van Ness Ave., Fresno, CA, 93728

VICTIM:

REPORTING OFFICER:

Wilding, Lee #F634

SYNOPSIS

This incident involves a fire which occurred within an occupied residential structure.

The fire caused moderate fire damage.

There was one fatality, related to this fire incident, identified at the time of this report.

The classification of this fire is incendiary.

SOURCE OF ACTIVITY

On 1/20/16 at approximately 1511 hours FFD communications received a 911 telephone call reporting a fire at 648 N. Van Ness Ave., Fresno City, Fresno County. At approximately 1537 hours I was assigned to this incident to assist with the investigation. I responded code-2 and arrived on scene at approximately 1542 hours.

INVESTIGATION

Refer to my FFD Investigations report 16-003909.LW.11 for a full summary of my investigation.

Print Date: 6/17/2019 Page 8 of 9



911 H Street Fresno, CA 93721 (559) 621-4181 FAX (559) 498-4323

Apparatus Assigned to Incident

Apparatus ID E03	Dispatched 15:14:34	<u>Enroute</u> 15:14:57	<u>Arrived</u> 15:15.10	<u>Cleared</u> 17:29.25
E09	15:12:41	15:14:15	15:15.37	16:36.14
BC01	15:12:41	15:14:52	15:17,01	16:37.04
T04	15:12:41	15:14:01	15:17.21	16:36.23
104	15:17:51	15:17:55	15:17.57	20:23.17
E04	15:12:41	15:13:57	15:17.58	15:50.13
T09	15:12:41	15:13:55	15:18.04	16:16.45
BC03	15:15:39	15:17:26	15:21.18	16:39.37
101	15:28:27	15:31:09	15:39.24	20:23.51
102	15:37:25	15:37:28	15:42.53	20:28.57
T04	16:47:44	16:47:45	16:47.47	17:08.21
E05	15:12:41	15:13:47		15:14.38
E07	15:29:21	15:30:43		15:33.48
E05	15:29:21	15:31:43		15:33.02

Time: 06/18/2019 14:57:35 Event: 16-AC5831

				INCIDENT INFOR	MATION		
Receive Time) /	Clear Time		Call Taker		Position	
01/20/2016	15:19:12	1/21/2016	11:22:44 PM	SELLICK RT 10.5.17, YVONNE ID: D3009		CT13	
Classification		Priority	10	How Receive	Services		
2A		1		T	Police, Fire		
Address							
			AV, FRESNO				
Police Agenc	У _	District		Beat	Station	Zone	
PD		SW		В	This Copy was prep	pared by the Fresno Police	
Fire Agency		District		Beat	Department on (Da	e) 2019	
					For the official use		
				SYNOPSIS			
FED REO P	D SHUT DOV	VN VAN NE	SS RETW VAN	NESS /BREMER FOR F		lews	
TI D KLQT	D GIIGT DOV	THE VALLE	DO BETTY VAI	THESO / BICEMIER TORY		vealed by any unauthorized pers	
				DISPOSITIO	By T364	vealed by any unauthorized pers	
Closing Class	Event Dispo	Location	Unit Code	Agency: Case Number	Primary Staff		
1D0	С	R	80	PD: 16-004815	MARTINEZ RT 3.5.19	9, LEO L. P168	
Closing Class	Event Dispo	Location	Unit Code	Agency: Case Number	Primary Staff		
MANT	1			FD:			
			mo	T DISTORIES (CL	DOLENENTS		
	4-6-3		1	T HISTORIES / SU	IELT - MEM 12		
Time	45.00.00	Unit	Status	Operator		Position	
01/20/2016	15:23:06	1C11	D	GUERRERO (V3048),	GINA ID: D3018	PD01	
Time	45.00.00	Unit	Status	Operator		Position	
01/20/2016	15:23:08	1C11	ER	GUERRERO (V3048), GINA ID: D3018		PD01	
Time 01/20/2016 15:23:12		Operator	CINA ID- D2049	Position PD01			
Supplement	15:23:12			GUERRERO (V3048),	GINA ID: D3018	PD01	
P2 ALLD ,V	01.2						
Time	U L.	Unit	Status	Operator		Position	
01/20/2016	15:26:28	1C11	AR	GRAZIER (V3140), R.	DAVID ID: P1040	A00575	
Time		diameter control		Operator		Position	
01/20/2016	15:29:49			SELLICK RT 10.5.17,	YVONNE ID: D3009	CT13	
Supplement						1	
P1 PD01 ,C	APT ON SCE	NE REQ AN	IOTHER UNIT	, UNK WHY			
Time ,				Operator		Position	
01/20/2016	15:30:16			SELLICK RT 10.5.17, YVONNE ID: D3009		CT13	
Supplement							
The second secon	DID SOMEON	NE CALL EI	AS ABOUT AN	OTHER HOUSE CATCH	ING FIRE NEAR THIS L	OCATION?	
Time		Unit	Status	Operator		Position	
01/20/2016	15:30:35	1C12	D	GUERRERO (V3048),	GINA ID: D3018	PD01	
Time	45.00.40	Unit	Status	Operator	LEGI ID DAGS	Position	
01/20/2016	15:30:42	1C12	AR	MARTINEZ RT 3.5.19,	LEU L. ID: P168	A00349	
Time 01/20/2016 15:31:03		Operator GUERRERO (V3048), GINA ID: D3018		Position			
Supplement	10:01:03			GUERKERU (V3048),	GINA ID: D3018	PD01	
	HIS SUBJETH	AT THEY D	ULLED OUT (OF BURNING BUILDING	APPEARS TO HAVE		
Time		Unit	Status	Operator	ALLENIO TO TAVE	Position	
01/20/2016	15:31:13	14	D	GUERRERO (V3048),	GINA ID: D3018	PD01	
Time		Unit	Status	Operator		Position	
01/20/2016	15:31:14	14	ER	GUERRERO (V3048),	GINA ID: D3018	PD01	
Time		Unit	Status	Operator	Principal Section (Contraction Contraction	Position	
01/20/2016	15:31:14	14	AR	GUERRERO (V3048),	GINA ID: D3018	PD01	
Time				Operator		Position	
01/20/2016 15:31:23				BABCOCK (V3153), T.	AMARA ID: D3090	CT08	

Time: 06/18/2019 14:57:35 Event: 16-AC5831

1110.00/10/2010 1-	1.01.00			EVEIL. 10-70000
Supplement	DITIONAL	NIT FOR 4		
P2 PD01 ,EMS REQ AD	DITIONAL U	NII FOR 1	Occuptor	D-W-
Time			Operator	Position
01/20/2016 15:31:53			GUERRERO (V3048), GINA ID: D3018	PD01
Supplement	_	4000 400	UD ZOAL CORIEC	
SUBJ W/	111.11		VD 701L COPIES	Ta :::
Time	Unit	Status	Operator	Position
01/20/2016 15:33:23	1H11	D	GUERRERO (V3048), GINA ID: D3018	PD01
Time	Unit	Status	Operator	Position
01/20/2016 15:33:29	1H11	ER	FERN RT 7.24.18, CHRISTOPHER ID: P759	A00464
Time	Unit	Status	Operator	Position
01/20/2016 15:33:42	PIO1	D	GUERRERO (V3048), GINA ID: D3018	PD01
Time	Unit	Status	Operator	Position
01/20/2016 15:34:09	FAX11	D.	GUERRERO (V3048), GINA ID: D3018	PD01
Time	Unit	Status	Operator	Position
01/20/2016 15:34:11	FAX11	AR	GUERRERO (V3048), GINA ID: D3018	PD01
Time	Unit	Status	Operator	Position
01/20/2016 15:34:31	1038	D	GUERRERO (V3048), GINA ID: D3018	PD01
Гime	Unit	Status	Operator	Position
01/20/2016 15:34:59	1H11	D	GUERRERO (V3048), GINA ID: D3018	PD01
Time	Unit	Status	Operator	Position
01/20/2016 15:35:02	1H11	CL	GUERRERO (V3048), GINA ID: D3018	PD01
Location			10	
CRMC				
Time	Unit	Status	Operator	Position
01/20/2016 15:35:06	1H11	ER	FERN RT 7.24.18, CHRISTOPHER ID: P759	A00464
Location	1,,			· · · · · · · · · · · · · · · · · · ·
CRMC				
Time	Unit	Status	Operator	Position
01/20/2016 15:36:20	12	AR	JOHNSON (V3053), TRACY ID: DT007	CT17
Time	Unit	Status	Operator	Position
01/20/2016 15:36:20	12	D	JOHNSON (V3053), TRACY ID: DT007	CT17
Time	Unit	Status	Operator	Position
01/20/2016 15:36:20	12	ER	JOHNSON (V3053), TRACY ID: DT007	CT17
Time			Operator	Position
01/20/2016 15:36:49			JOHNSON (V3053), TRACY ID: DT007	CT17
Supplement			, , , , , , , , , , , , , , , , , , , ,	, 0
• •	ON THE AL	R FOR THIS	TO LL FIRE INVESTIGATOR 12 # IN LOG ON	
Time			Operator	Position
01/20/2016 15:37:36			GUERRERO (V3048), GINA ID: D3018	PD01
Supplement			GOZINIZNO (VOCTO), CINTA ID. DOCTO	11001
SVB ADVD				
Time	1		Operator	Position
01/20/2016 15:38:02			GUERRERO (V3048), GINA ID: D3018	PD01
Supplement			GOERRERO (VOO40), CHAN ID. DOUTO	1 - 501
P2 CT13 ,DETS ARE A	DVD			î
Time	Unit	Status	Operator	Position
01/20/2016 15:38:14	103S	ER	GUERRERO (V3048), GINA ID: D3018	PD01
	1033	EK		
Time			Operator	Position
01/20/2016 15:38:48			GUERRERO (V3048), GINA ID: D3018	PD01
Supplement	OF THIS EV	AIT		
P2 COMS03 ,BE ADVD	OF THIS EV	IN I		
Time			Operator	Position
-			ALIEDBERG MACCOL COLL. IS SECTION	
Time 01/20/2016 15:39:14 Supplement		-	GUERRERO (V3048), GINA ID: D3018	PD01

Time: 06/18/2019 14:57:35 Event: 16-AC5831 Unit Status Operator Position 01/20/2016 15:40:18 1H11 AR FERN RT 7.24.18, CHRISTOPHER ID: P759 A00464 Location CRMC Unit Status Operator Position Time 01/20/2016 15:42:27 704L ER RAMOS (V3022), DAVE ID: L46 A00607 Location 648 N VAN NESS AV / E BELMONT AV Operator Position 01/20/2016 15:44:32 ROBERTS (V3066), LINDA ID: D3005 **CT03** Supplement EMS: UNIT 117 PARAMEDIC SANDRA CASTRO AND EMT KAYLA OLSON, UNIT 119 PARAMEDIC ROSALIO FLORES ,EMT IAN **ASHBY** Unit Status Operator Position 01/20/2016 15:49:14 704L AR RAMOS (V3022), DAVE ID: L46 A00607 Location 648 N VAN NESS AV / E BELMONT AV Time Unit Status Operator Position 01/20/2016 15:49:41 103S AR GUERRERO (V3048), GINA ID: D3018 **PD01** Time Operator Position 01/20/2016 15:54:57 **GUERRERO (V3048), GINA ID: D3018 PD01** Supplement P2 ALLD ,UNIT TO ASSIST OF CRIME SCENE ENTER EAST OR WEST OFF OF BREMER Status Time Unit Operator Position D 01/20/2016 15:55:21 6H12 GARZA (V3045), JUDY ID: D3011 **PD08** Status Unit Operator Position Time 6H12 01/20/2016 15:55:23 ER GARZA (V3045), JUDY ID: D3011 PD08 Time Operator Position ROBERTS (V3066), LINDA ID: D3005 01/20/2016 15:56:37 **CT03** Supplement FFD: BC1 TODD TUGGLE,BC3 CHARLES TOBIAS, E3: CAPT CHRISTIAN PALMER, ENGINEER JEREMY TATHAM, FF JAMES PERKINS, FF LOUIE GONZALEZ, E4: CAPT TIMOTHY FULMER, ENG ROBERT GARCIA, FF TIMOTHY OTTO E5: CAPT BARTON BURKHART, ENG JEFFERY FARIGONI, ENG JEFFERY CRASK, FF KENNETH GARCIA, FF MICHAEL BOARDMAN, FF MARTIN GARCIA Position Time Operator 01/20/2016 15:56:45 ROBERTS (V3066), LINDA ID: D3005 **CT03** Supplement FFD: E7: CAPT DOUGLAS GARISO, ENG MICHAEL RESSLER, FF MICHAEL MCLNTYRE E9: CAPT JOHN DOLAN, ENG RAFAEL **ENCIZO, FF MICHAEL ALVAREZ, 11:** Operator Position 01/20/2016 15:59:14 **GUERRERO (V3048), GINA ID: D3018** PD01 Supplement 1C11 Comment: 1 BODY N/END 1 FOR S/END ... 1 CRIME SCENE LOG Unit Status Operator Position 01/20/2016 16:00:36 1R21 n GUERRERO (V3048), GINA ID: D3018 PD01 Status Time Unit Operator Position 01/20/2016 16:00:44 1B21 HOLGUIN (V3764), GIL ID: P1003 A00528 ER Time Position 01/20/2016 16:02:18 ROBERTS (V3066), LINDA ID: D3005 **CT03** Supplement 11 RICHARD PEREZ, 12 LEE WEILDING, 14 JAY TRACY, T4:CAPT ROBERT VANTASSEL, ENG WALTER SICKLER, RESCUE ENG CODY PHILBIIN, FF FRANK MONTERROSA T9: CAPT NICHOLAS MARTINO ,ENG WILLIAM GADE, FF JEFFERY ROE, FF CLAYTON ALLISON Operator Position 01/20/2016 16:02:31 ROBERTS (V3066), LINDA ID: D3005 **CT03** Supplement P2 PD01 .CALL UPDATED W/EMS FFD PERSONNEL

Time: 06/18/2019 14	1.57.25		Event Report	Fuent: 16 ACES
Time. 00/10/2019 12	4.57.35 Unit	Status	Operator	Event: 16-AC583
01/20/2016 16:06:22	1B21	AR	HOLGUIN (V3764), GIL ID: P1003	A00528
ime	Unit	Status	Operator	Position
1/20/2016 16:06:57	PIO1	ER	GOMEZ RT 4.1.19, JOE ID: L43	A00605
ime	Unit	Status	Operator	Position
1/20/2016 16:08:50	6H20	D	TAKAYAMA (V3084), SHARON ID: D3010	PD01
ime	Unit	Status	Operator	Position
1/20/2016 16:08:52	6H20	ER	TAKAYAMA (V3084), SHARON ID: D3010	PD01
ime	Unit	Status	Operator	Position
1/20/2016 16:08:52	6H20	AR	TAKAYAMA (V3084), SHARON ID: D3010	PD01
ime	Unit	Status		Position
01/20/2016 16:10:36	PIO1	AR	Operator	
			GOMEZ RT 4.1.19, JOE ID: L43	A00605
ime	Unit	Status	Operator	Position
01/20/2016 16:10:47	PIO1	CL	GOMEZ RT 4.1.19, JOE ID: L43	A00605
ocation CRMC				
	11-4	Olotos		
ime	Unit	Status	Operator	Position
01/20/2016 16:10:55	PIO1	AR	GOMEZ RT 4.1.19, JOE ID: L43	A00605
ocation				
ime			Occupies	De silie e
)1/20/2016 16:11:21			Operator	Position
			TAKAYAMA (V3084), SHARON ID: D3010	PD01
Supplement				
S1 ADV	T			
ime	Unit	Status	Operator	Position
01/20/2016 16:19:46	PIO1	CL	GOMEZ RT 4.1.19, JOE ID: L43	A00605
_ocation			Ē)	
648 N. VAN NESS	1	T		
Time	Unit	Status	Operator	Position
01/20/2016 16:22:31	1C11	CL	GRAZIER (V3140), R. DAVID ID: P1040	A00575
_ocation				
SW	T			
Time	Unit	Status	Operator	Position
01/20/2016 16:23:01	PIO1	AR	GOMEZ RT 4.1.19, JOE ID: L43	A00605
ocation				
648 N. VAN NESS	1			
îme	Unit	Status	Operator	Position
01/20/2016 16:23:03	107S	D	TAKAYAMA (V3084), SHARON ID: D3010	PD01
ime	,Unit	Status	Operator	Position
01/20/2016 16:23:05	107S	ER	TAKAYAMA (V3084), SHARON ID: D3010	PD01
Time	Unit	Status	Operator	Position
01/20/2016 16:23:30	1D22	D	TAKAYAMA (V3084), SHARON ID: D3010	PD01
_ocation				
CRMC				
Гime	Unit	Status	Operator	Position
01/20/2016 16:23:40	1D22	ER	GONZALES (V3248), STEVEN ID: P1225	A00362
ocation				
CRMC				
ime			Operator	Position
01/20/2016 16:24:33			GARZA (V3045), JUDY ID: D3011	PD08
Supplement				· · · · · · · · · · · · · · · · · · ·
P2 PD01 ,				
Гime	Unit	Status	Operator	Position
	1A21	D	TAKAYAMA (V3084), SHARON ID: D3010	PD01
01/20/2016 16:24:37	IMEI		I CONTROL VOUCE, SHANGIN ID. DOOLG	
01/20/2016 16:24:37 Location	IAZI		TAKATAMA (*3004), SHAKOK ID. D3010	1.001

Time: 06/18/2019 14:57:35 Event: 16-AC5831 Time Unit Status Operator Position 01/20/2016 16:24:38 1A21 ER TAKAYAMA (V3084), SHARON ID: D3010 **PD01** Location **BELMONT/VAN NESS** Unit Status Operator Position 01/20/2016 16:25:20 1C11 AR GRAZIER (V3140), R. DAVID ID: P1040 A00575 Location SW Unit Status Time Operator Position 01/20/2016 16:27:08 1A21 C3 HERNANDEZ (V3191), MICHAEL ID: P1119 A00448 Location **BELMONT/VAN NESS** Unit Status Operator Position AR 01/20/2016 16:27:10 107S GONZALES TM 10.27.18, ROBERT ID: S197 A00558 Unit Status Time Operator Position 01/20/2016 16:27:54 1A21 ER HERNANDEZ (V3191), MICHAEL ID: P1119 A00448 Location **BELMONT/VAN NESS** Unit Status Operator Position Time 01/20/2016 16:28:37 6H12 PD01 AR TAKAYAMA (V3084), SHARON ID: D3010 Unit Status Position 01/20/2016 16:29:26 1A21 AR HERNANDEZ (V3191), MICHAEL ID: P1119 A00448 Location BELMONT/VAN NESS Time Unit Status Operator Position 01/20/2016 16:29:49 1A22 D TAKAYAMA (V3084), SHARON ID: D3010 PD01 Location ALLEY N OF LOC Time Position Operator 01/20/2016 16:29:49 TAKAYAMA (V3084), SHARON ID: D3010 PD01 Supplement 1A22 Comment: BLOCK OFF N END AND S END Unit Status Operator Position 01/20/2016 16:29:55 1A22 ER STOCKDALE (V3628), RYAN ID: P1286 A00566 Location ALLEY N OF LOC Operator Position 01/20/2016 16:32:06 TAKAYAMA (V3084), SHARON ID: D3010 **PD01** Supplement P2 CT03 ,LL CITY ..BARRIERS OR BARACADES ?? .. NB VAN NESS AT BELMONT . PROB AT LEAST 2 Position 01/20/2016 16:34:32 CAMPOS (V3109), KALINDA ID: D3051 **CT03** Supplement P2 PD01,1A21 1100 ADVSD Unit Status Operator Position 01/20/2016 16:38:51 1A22 AR A00566 STOCKDALE (V3628), RYAN ID: P1286 Location ALLEY N OF LOC Unit Status Operator Position PD01 01/20/2016 16:40:08 1D22 D GUERRERO (V3048), GINA ID: D3018 Unit Status Position 01/20/2016 16:40:11 1D22 CL GUERRERO (V3048), GINA ID: D3018 PD01 Location CRMC Unit Status Operator Position Time 01/20/2016 16:40:29 1C12 CL MARTINEZ RT 3.5.19, LEO L. ID: P168 A00349

Time: 06/18/2019 14:57:35 Event: 16-AC5831 Location SW Unit Status Position Time Operator 1H11 CL A00464 01/20/2016 16:44:03 FERN RT 7.24.18, CHRISTOPHER ID: P759 SW Time Unit Status Operator Position 1C12 MARTINEZ RT 3.5.19, LEO L. ID: P168 A00349 01/20/2016 16:47:07 AR Location SW Position Time Operator 01/20/2016 16:48:22 GUERRERO (V3048), GINA ID: D3018 PD01 Supplement P2 ALLD , VOL CITY WIDE TO ASSIT ON THIS ? Position Time Operator PD01 01/20/2016 16:54:11 GUERRERO (V3048), GINA ID: D3018 Supplement P2 CT03, CB CITY ETA FOR BARRICADES PLEASE Operator Position Unit Status AR A00464 01/20/2016 16:56:04 1H11 FERN RT 7.24.18, CHRISTOPHER ID: P759 Location SW Position Time Operator 01/20/2016 16:57:25 **CT03** CAMPOS (V3109), KALINDA ID: D3051 Supplement P2 PD01, 1A21 PER 1100 THEIR SUPERVISOR IS RESPONDING TO LOC. THEY HAVE BEEN IN CONTACT W/FFD Unit Status Position Operator 1D22 CL **CT09** 01/20/2016 17:11:39 TAKAYAMA (V3084), SHARON ID: D3010 Location CRMC/LER Unit Status Position Operator 1A22 D PD01 01/20/2016 17:14:16 GUERRERO (V3048), GINA ID: D3018 Location BELMONT/VAN NESS Unit Status Operator Position 01/20/2016 17:14:24 1A22 ER GUERRERO (V3048), GINA ID: D3018 PD01 Location **BELMONT/VAN NESS** Position Operator Time 01/20/2016 17:19:40 GUERRERO (V3048), GINA ID: D3018 **PD01** Supplement 1A21 Comment: 1100 ARRIVED W/ BARRICADES Time Unit Status Operator Position AR A00566 01/20/2016 17:21:04 1A22 STOCKDALE (V3628), RYAN ID: P1286 Location **BELMONT/VAN NESS** Unit Status Operator Position 01/20/2016 17:33:41 6V14 D GUERRERO (V3048), GINA ID: D3018 PD01 Unit Status Operator Position 01/20/2016 17:33:41 PD01 6V15 D GUERRERO (V3048), GINA ID: D3018 Unit Status Position 01/20/2016 17:33:47 6V14 AR GUERRERO (V3048), GINA ID: D3018 PD01 Time Unit Status Operator Position 01/20/2016 17:33:47 ER PD01 6V15 GUERRERO (V3048), GINA ID: D3018 Unit Status Operator Position 6V15 AR GUERRERO (V3048), GINA ID: D3018 PD01 01/20/2016 17:33:47

Time: 06/18/2019 14:57:35 Event: 16-AC5831 Time Unit Status Operator Position 01/20/2016 17:33:47 6V14 GUERRERO (V3048), GINA ID: D3018 PD01 ER Position Time Operator 01/20/2016 17:38:30 NAVARRO (V3414), KANDA ID: D3050 **CT04** Supplement 6H12 Comment: IB EVT AC6050 Unit Status Operator Position 01/20/2016 17:45:59 6121 D GUERRERO (V3048), GINA ID: D3018 PD01 Unit Status Operator Position Time 6121 B50054 01/20/2016 17:46:08 ΕR VALDEZ (V3581), PATTY ID: ID95 Status Unit Position Time Operator CL 01/20/2016 17:46:13 6121 B50054 VALDEZ (V3581), PATTY ID: ID95 Location CRMC Unit Time Status Operator Position 01/20/2016 17:46:33 6121 ER VALDEZ (V3581), PATTY ID: ID95 B50054 Location CRMC Unit Status Operator Position VALDEZ (V3581), PATTY ID: ID95 01/20/2016 17:49:38 6121 AR B50054 Location CRMC Operator Position Time 01/20/2016 17:53:03 NELSON TM 10.12.18, DARREN ID: P1409 A00448 Supplement EAST VANNESS/BELMONT ALLEY WAY Unit Status Operator Position Time 01/20/2016 17:53:30 AR NELSON TM 10.12.18, DARREN ID: P1409 A00448 1A21 Location EAST VANNESS/BELMONT ALLEY WAY Unit Status Operator Position 01/20/2016 18:19:58 6V12 D GARZA (V3045), JUDY ID: D3011 PD08 Unit Status Operator Position 01/20/2016 18:19:59 6V12 ER GARZA (V3045), JUDY ID: D3011 PD08 Status Unit Operator Position 01/20/2016 18:19:59 6V12 AR GARZA (V3045), JUDY ID: D3011 **PD08** Unit Status Position 01/20/2016 18:21:24 6V12 **ECOMM** GUERRERO (V3048), GINA ID: D3018 PD01 Comment License Plate Check LIC:3UDV980 LIS:CA Request Key:26789766 Unit Status Position Time Operator 01/20/2016 19:09:43 PD01 6121 D DEALBA PM 1.21.19, ANITRA ID: D3036 Unit Status Time Operator Position 01/20/2016 19:09:51 6121 ER VALDEZ (V3581), PATTY ID: ID95 B50054 Time Unit Status Operator Position 01/20/2016 19:20:03 6121 AR VALDEZ (V3581), PATTY ID: ID95 B50054 Unit Status Position Operator 01/20/2016 20:27:03 B50054 6121 CL VALDEZ (V3581), PATTY ID: ID95 Location **CSIB** Unit Status Operator Position 01/20/2016 20:27:09 6121 AR B50054 VALDEZ (V3581), PATTY ID: ID95 Location **CSIB**

Time: 06/18/2019 14:57:35 Event: 16-AC5831 Time Unit Status Operator Position 01/20/2016 21:08:20 6121 CL VALDEZ (V3581), PATTY ID: ID95 B50054 Location 648 N VAN NESS Unit Status Operator Position 6121 B50054 01/20/2016 21:11:42 AR VALDEZ (V3581), PATTY ID: ID95 Location 648 N VAN NESS Time Operator Position 01/20/2016 21:29:59 VASQUEZ (V3194), NOZOMI ID: D3108 **CT11** Supplement P2 PD01, OF VICTIM....WANTED TO SPEAK WITH DETECTIVE ON SCENE CONT Unit Time Status Operator Position 01/20/2016 21:43:41 6H20 AR YANG (V3094), MAY-YEN ID: D3024 **CT09** Location HQ Time Unit Status Operator Position DEALBA PM 1.21.19, ANITRA ID: D3036 01/20/2016 22:41:02 6126 ER PD01 Status Time Unit Operator Position PD01 01/20/2016 22:41:02 6126 D DEALBA PM 1.21.19, ANITRA ID: D3036 Status Position Time Unit Operator 01/20/2016 22:43:50 6126 AR DEALBA PM 1.21.19, ANITRA ID: D3036 PD01 Unit Status Operator Position FLORES XF 1.7.19, BEN ID: D3110 01/21/2016 00:26:46 6126 ER PD01 Unit Status Position Operator 01/21/2016 00:27:00 6126 ER FLORES XF 1.7.19, BEN ID: D3110 PD01 Location 648 N VAN NESS Unit Status Position Time Operator 01/21/2016 00:29:59 6126 AR FLORES XF 1.7.19, BEN ID: D3110 **PD01** Location 648 N VAN NESS Time Unit Status Operator Position 01/21/2016 00:40:20 1F31 ER FLORES XF 1.7.19, BEN ID: D3110 PD01 Unit Status Position Time Operator 1F31 AR URTON (V3730), BRYON ID: P983 A00513 01/21/2016 00:46:54 Unit Status Operator Position Time 01/21/2016 01:10:08 1B21 CL HOLGUIN (V3764), GIL ID: P1003 A00528 Location CITY SHOP Time Position 01/21/2016 01:14:02 URTON (V3730), BRYON ID: P983 A00513 Supplement CRIME SCENE LOG.... B. URTON #983/ 1F31 Status Operator Position Unit 01/21/2016 01:20:09 1B21 AR HOLGUIN (V3764), GIL ID: P1003 A00528 Location CITY SHOP Time Unit Status Operator Position 01/21/2016 01:26:23 1B21 CL HOLGUIN (V3764), GIL ID: P1003 A00528 Location SW Time Unit Status Operator Position 01/21/2016 01:26:29 1B21 AR HOLGUIN (V3764), GIL ID: P1003 A00528 Location SW

Time: 06/18/2019 14:57:35 Event: 16-AC5831 Time Unit Status Operator Position 01/21/2016 01:29:20 6121 CL VALDEZ (V3581), PATTY ID: ID95 B50054 Location **CSIB** Unit Position Status Operator B50054 01/21/2016 01:29:23 6121 AR VALDEZ (V3581), PATTY ID: ID95 Location **CSIB** Unit Status Operator Position Time 01/21/2016 01:36:45 1A22 CL STOCKDALE (V3628), RYAN ID: P1286 A00566 Location SW Position Operator Time PD01 01/21/2016 01:38:04 BAILLY RS 12.10.16, KARA ID: D3093 Supplement P2 CT03, PLZ LL 1100 SEE IF THEY CAN COME PU THEIR BARRICADES Operator Position GARVEY (V3326), NORMA ID: D3056 01/21/2016 01:39:16 **CT03** Supplement P2 PD01,1F31...1100 ADVD Unit Status Operator Position 01/21/2016 01:43:03 1A22 A00566 AR STOCKDALE (V3628), RYAN ID: P1286 Location SW Position Time Operator PD01 01/21/2016 01:53:35 BAILLY RS 12.10.16, KARA ID: D3093 Supplement P2 CT03, EVIDENCE TOW PLACE PLATE HOLD FOR HOMICIDE Position Unit Status Time Operator 1A21 CL NELSON TM 10.12.18, DARREN ID: P1409 A00448 01/21/2016 01:54:59 Location SW Unit Status Operator Position 3D31 PD01 01/21/2016 01:55:15 D BAILLY RS 12.10.16, KARA ID: D3093 Operator Position 01/21/2016 01:55:19 GARVEY (V3326), NORMA ID: D3056 **CT03** Supplement P2 PD01 ,1F31...EVIDENCE TOW STARTED Unit Status Position Operator Time 3D31 A00547 01/21/2016 01:58:47 ER PAP (V3934), MATTHEW ID: P1465 Time Unit Status Position 01/21/2016 01:59:52 1A21 AR NELSON TM 10.12.18, DARREN ID: P1409 A00448 Location SW Unit Status Position Operator 3D31 AR A00547 01/21/2016 02:07:27 PAP (V3934), MATTHEW ID: P1465 Unit Status Position Time Operator 6121 B50054 01/21/2016 03:00:58 CL VALDEZ (V3581), PATTY ID: ID95 Location 648 N VAN NESS Unit Status Operator Position 01/21/2016 03:09:13 6121 AR VALDEZ (V3581), PATTY ID: ID95 B50054 Location 648 N VAN NESS Unit Position Status Operator B50054 01/21/2016 03:38:30 6121 CL VALDEZ (V3581), PATTY ID: ID95

Time: 06/18/2019 14:57:35 Event: 16-AC5831

Time	Unit	Status	Operator	Position
01/21/2016 03:44:10	6121	AR	VALDEZ (V3581), PATTY ID: ID95	B50054
Location				
CSIB				
Time	Unit	Status	Operator	Position
01/21/2016 03:48:21	1B31	D	DEALBA PM 1.21.19, ANITRA ID: D3036	PD01
Time	Unit	Status	Operator	Position
01/21/2016 03:50:02	1B31	ER	KONG (V3303), ERIC ID: P1218	A00475
Time	Unit	Status	Operator	Position
01/21/2016 03:51:24	1B31	AR	KONG (V3303), ERIC ID: P1218	A00475
Time	Unit	Status	Operator	Position
01/21/2016 06:51:56	1C12	D	LANDIN RS 12.23.16, ANGIE ID: D3037	PD01
Time	Unit	Status	Operator	Position
01/21/2016 06:52:08	1C12	ER	MARTINEZ RT 3.5.19, LEO L. ID: P168	A00349
Time	Unit	Status	Operator	Position
01/21/2016 06:55:25	1C12	AR	MARTINEZ RT 3.5.19, LEO L. ID: P168	A00349
Time	Unit	Status	Operator Control Contr	Position
01/21/2016 07:08:28	1E11	D	GUZMAN (V3049), RAFAEL ID: D3039	PD01
Time	Unit	Status	Operator	Position
01/21/2016 07:08:42	1E11	ER	CONLEE RT 9.6.17, JOHN R ID: P208	A00283
Time	Unit	Status	Operator	Position
01/21/2016 07:12:30	1B31	ER	KONG (V3303), ERIC ID: P1218	A00475
Location NE				
	11-14	Ctatus	0	Position
Time 01/21/2016 07:19:13	Unit 1E11	Status AR	Operator	A00283
Time	Unit	Status	CONLEE RT 9.6.17, JOHN R ID: P208	Position
01/21/2016 07:22:36	1F31	CL	Operator URTON (V3730), BRYON ID: P983	A00513
Location	11 31	- CL	OKTON (43730), BRTON ID. F303	A00313
SW				
Time	Unit	Status	Operator	Position
01/21/2016 07:23:55	1B31	AR	KONG (V3303), ERIC ID: P1218	A00475
Location	,	, , , , ,	,	, , , , , , , , , , , , , , , , , , , ,
NE				
Time	Unit	Status	Operator	Position
01/21/2016 07:29:53	1F31	AR	URTON (V3730), BRYON ID: P983	A00513
Location		,		
sw				
Time	Unit	Status	Operator	Position
01/21/2016 07:43:57	6119	D	GUZMAN (V3049), RAFAEL ID: D3039	PD01
Time	Unit	Status	Operator	Position
01/21/2016 07:44:00	6119	ER	INGHAM RS 12.16.17, DAVID ID: ID96	B50038
Time	Unit	Status	Operator	Position
	6119	AR	INGHAM RS 12.16.17, DAVID ID: ID96	B50038
01/21/2016 07:50:39	Unit	Status	Operator	Position
Time	1G15	D	GUZMAN (V3049), RAFAEL ID: D3039	PD01
Time 01/21/2016 09:09:06			Operator	Position
Time 01/21/2016 09:09:06 Time	Unit	Status		
Time 01/21/2016 09:09:06 Time 01/21/2016 09:09:15	Unit 1G15	AR	PINEDO (V3307), JOHN M ID: P611	A00464
01/21/2016 09:09:06 Time 01/21/2016 09:09:15 Time	Unit 1G15 Unit	AR Status	PINEDO (V3307), JOHN M ID: P611 Operator	A00464 Position
Time 01/21/2016 09:09:06 Time 01/21/2016 09:09:15 Time 01/21/2016 11:19:52	Unit 1G15	AR	PINEDO (V3307), JOHN M ID: P611	A00464
Time 01/21/2016 09:09:06 Time 01/21/2016 09:09:15 Time 01/21/2016 11:19:52 Comment	Unit 1G15 Unit 1C12	AR Status ECOMM	PINEDO (V3307), JOHN M ID: P611 Operator MARTINEZ RT 3.5.19, LEO L. ID: P168	A00464 Position
Time 01/21/2016 09:09:06 Time 01/21/2016 09:09:15 Time 01/21/2016 11:19:52	Unit 1G15 Unit 1C12	AR Status ECOMM	PINEDO (V3307), JOHN M ID: P611 Operator MARTINEZ RT 3.5.19, LEO L. ID: P168	A00464 Position

Time: 06/18/2019 14:57:35 Event: 16-AC5831 Status Time Unit Operator Position 01/21/2016 12:12:32 1C12 AR A00349 MARTINEZ RT 3.5.19, LEO L. ID: P168 Unit Status Operator Position 01/21/2016 14:48:04 1G15 D ESCARENO RS 9.5.18, MARIBEL ID: D3038 PD01 Unit Status Operator Position 01/21/2016 14:48:20 1G15 AR A00464 PINEDO (V3307), JOHN M ID: P611 Operator Position 01/21/2016 15:25:46 MARTINEZ RT 3.5.19, LEO L. ID: P168 A00349 Supplement CODE ENFORCEMENT ARRIVED TO BOARD UP THE RESIDENCE. Unit Status Position 01/21/2016 16:15:07 1E11 CL CONLEE RT 9.6.17, JOHN R ID: P208 A00283 Location SW Unit Status Time Operator Position 01/21/2016 16:22:16 1E11 AR CONLEE RT 9.6.17, JOHN R ID: P208 A00283 Location SW Time Unit Status Operator Position 01/21/2016 16:23:28 1C12 CL MARTINEZ RT 3.5.19, LEO L. ID: P168 A00349 Location SW Unit Status Operator Position 01/21/2016 16:25:51 1C12 AR A00349 MARTINEZ RT 3.5.19, LEO L. ID: P168 Location SW Unit Time Dissociate Status 01/20/2016 22:52:09 6126 IN Dissociate Status Unit 01/20/2016 15:34:13 1H11 IN Dissociate Status Unit Time 01/20/2016 15:53:18 FAX11 IN Dissociate Status Unit 01/20/2016 16:25:43 1C11 OFF Unit Dissociate Status Time 01/20/2016 16:29:49 1D22 IN Dissociate Status Time Unit 01/20/2016 16:39:51 1A22 IN Unit Dissociate Status Time OFF 01/20/2016 16:41:23 **103S** Time Unit Dissociate Status 01/20/2016 16:56:09 1H11 Unit Dissociate Status Time 01/20/2016 17:26:39 704L IN Unit Dissociate Status Time 01/20/2016 17:28:11 PIO1 IN Time Unit Dissociate Status 01/20/2016 17:31:53 1C12 IN Unit Dissociate Status 01/20/2016 17:34:21 107S Time Unit Dissociate Status 01/20/2016 18:12:41 6121 IN Time Unit Dissociate Status 01/20/2016 18:13:33 1D22

Time: 06/18/2019 14:57:35 Event: 16-AC5831 Time Unit Dissociate Status 01/20/2016 19:18:15 6V12 Dissociate Status Unit Time 01/20/2016 21:05:37 12 OFF Dissociate Status Unit Time 01/20/2016 21:05:37 14 OFF Dissociate Status Time Unit 01/21/2016 10:46:10 1G15 Dissociate Status Unit Time 01/21/2016 10:54:52 6119 IN Dissociate Status Time Unit OFF 01/21/2016 11:03:55 6V15 Dissociate Status Unit Time 01/21/2016 11:03:57 6V14 OFF Dissociate Status Unit Time 6H12 01/21/2016 23:21:32 Unit Dissociate Status Time 6126 01/21/2016 00:34:03 IN Time Unit Dissociate Status 1B21 5AOF 01/21/2016 01:42:14 Unit Dissociate Status Time 01/21/2016 01:51:37 1A22 IN Unit Dissociate Status 1A21 01/21/2016 02:00:06 Unit Dissociate Status Time 01/21/2016 15:13:20 1G15 Dissociate Status Time Unit 01/21/2016 03:20:46 6H20 OFF Dissociate Status Unit Time 6121 IN 01/21/2016 03:44:14 Time Unit Dissociate Status 01/21/2016 16:24:37 1E11 Unit Dissociate Status Time 01/21/2016 16:26:12 1C12 IN Unit Dissociate Status 01/21/2016 04:39:02 3D31 ΙN Dissociate Status Unit OFF 01/21/2016 07:29:50 1B31 Unit Dissociate Status 01/21/2016 07:31:31 1F31 OFF STAFF Fire Unit WILDING (FFD), F LELAND ID: F634 12 Fire Unit 14 TRACY (FFD), JAY S. ID: F685 Police Unit **103S** MERCADO RT 8.9.18, ANDREW ID: S79 Police Unit GONZALES TM 10.27.18, ROBERT ID: S197 107S Police Unit HERNANDEZ (V3191), MICHAEL ID: P1119 1A21 NELSON TM 10.12.18, DARREN ID: P1409 Police Unit 1A21 NELSON TM 10.12.18, DARREN ID: P1409

Time: 06/18/2019 14:57:35 Event: 16-AC5831 Police Unit Staff 1A22 STOCKDALE (V3628), RYAN ID: P1286 Police Unit 1B21 HOLGUIN (V3764), GIL ID: P1003 HOWARD (V3933), CRAIG ID: P1306 Police Unit 1B31 KONG (V3303), ERIC ID: P1218 Police Unit 1C11 GRAZIER (V3140), R. DAVID ID: P1040 Police Unit 1C12 MARTINEZ RT 3.5.19, LEO L. ID: P168 Police Unit 1D22 GONZALES (V3248), STEVEN ID: P1225 Police Unit CONLEE RT 9.6.17, JOHN R ID: P208 1E11 Police Unit URTON (V3730), BRYON ID: P983 1F31 LAMBERT (V3247), DAVID ID: P742 Police Unit Staff 1G15 PINEDO (V3307), JOHN M ID: P611 Police Unit 1H11 FERN RT 7.24.18, CHRISTOPHER ID: P759 Police Unit 3D31 PAP (V3934), MATTHEW ID: P1465 Police Unit Staff 6H12 DODD (V2478), KENNETH G ID: P280 Police Unit BOWLAN PM 9.17.18, LARRY ID: \$168 6H20 Police Unit Staff INGHAM RS 12.16.17, DAVID ID: ID96 6119 DESOTO (V3783), CYNTHIA ID: ID36 Police Unit 6121 VALDEZ (V3581), PATTY ID: ID95 Police Unit 6126 MAY (V3331), R SCOTT ID: ID85 Police Unit 6V12 SUAREZ PM 12.26.16, EZEQUIEL ID: P1074 Police Unit 6V14 KNAPP (V3977), JOSHUA ID: P1423 Police Unit 6V15 BROWN (V3202), BRANDON ID: P1430 Police Unit 704L RAMOS (V3022), DAVE ID: L46 Police Unit FAX11 RUIZ PROMO 1.8.18, RUDY C ID: P379 Police Unit PIO₁ GOMEZ RT 4.1.19, JOE ID: L43 RESPONSE TIMES Event Police Fire 01/20/2016 15:19:12 01/20/2016 15:20:00 Receive

Time: 06/18/201	Event: 16-AC5831			
Save	01/20/2016 15:20:19			
Dispatch	01/20/2016 15:23:06	01/20/2016 15:23:06		
Enroute	01/20/2016 15:23:08	01/20/2016 15:23:08		
Arrive	01/20/2016 15:26:28	01/20/2016 15:26:28		
Last Clear	01/21/2016 23:21:32	01/21/2016 23:21:32		
No. of Units	28	26	2	

Time: 06/18/2019 14:58:22 Event: 16-AC6050

				INCIDENT INFOR	MATION		
Receive Time 01/20/2016		Clear Time 1/20/2016 5:46:05 PM		Call Taker NAVARRO (V3414), KA	ANDA ID: D3050	Position CT04	
Classification 5AIB		Priority 1		How Receive T	Services Police		
Place/Busines							
Address 140 N CLAR	RK ST / E ILL	INOIS AV, FI	RESNO				
Police Agency	Police Agency District			Beat D	Station	Zone 2556	
				SYNOPSIS	S	A PROPERTY OF THE PARTY.	
NEED IB PE	R 6H12, EV	AC5831, CI	RMC LER				
				DISPOSITIO	ONS		
Closing Class	Event Dispo	Location	Unit Code	Agency: Case Number PD:	Primary Staff		
			UN	IT HISTORIES / SU	PPLEMENTS		
Time 01/20/2016	17:39:07			Operator NAVARRO (V3414), KA	ANDA ID: D3050	Position CT04	
Supplement IB ADVSD							
	3.74			RESPONSE T	IMES		
		Event		Police	Fire		
Receive		01/20/2016	17:37:58	01/20/2016 17:38:09			
Save	01/20/2016 17:38:21						
Dispatch							
Enroute							
Arrive							
Last Clear							
No. of Unite	No of Unite 0		0	0			

This Copy was prepared	by the Fresno Police	
Department on (Date)	6-18-2019	
For the official use of: Name_ Kim Crooks		
AgencyMuckRock News		
and may not be revealed	ed by any unauthorized	person
By T364		